

SITE VISIT RECORD

Site Visit Photographs



Photograph 1: Brickwork repairs on-going to Art Block.



Photograph 2: Roof 7 - Works nearing completion.



Photograph 3: English block, Asbestos containing cladding removal commenced.



Photograph 4: Cladding installation complete to North Elevation.



Photograph 5 - HSC Block - New Velux installations and artificial slates



Photograph 6 - MFL toilets reconfiguration Steel installed.